



Infra-red thermometers with laser sight



Meter type infra-red thermometer

Features:

- auto power-off
- laser sight
- HOLD function
- MAX function
- selection of Celsius or Fahrenheit units
- double backlit LCD
- constant measurement (interlocking of measurement release button)
- adjustable emissivity
- low battery indicator

Optical resolution	20:1
Emissivity value	0,1...1
Emissivity resolution	0,01
Non-contact temperature measuring range	-50..800°C
Non-contact temperature measuring resolution	0,1°C
Non-contact temperature measuring accuracy	±(1.0% +1.0°C)
Response time	<0.15 s
Power supply	1 battery 9V 6F22
Equipment	case

Symbol	Product description
AX-7531	Pyrometer with emissivity adjustable and laser

© PARCAT Parametric Catalogue: www.parcat.eu